

Paasche®

DC150 Compressor

110-120Volts, 50/60Hz, 1.6 Amps

Shipping Weight: 1.70 Lbs (.77 kgs).

2-15 PSI (Gravity Airbrush .38mm or smaller)

UL, CE, GS & ROHS

Features:

1. Compatible with gravity feed airbrushes with .38mm Heads or smaller
2. Recommended for makeup or other low PSI applications
3. Oilless operation
4. Very little noise
5. Three Pressure levels with steady pressure output
6. Built in airbrush holder

Operating Instructions:

1. Attach AC power plug into compressor then plug into (110-120 volt) power socket.
2. Connect Air hose(Included) to 1/8" BPS male fitting on compressor and the other end to your airbrush.
3. Hidden airbrush cradle, rotate out and attach Airbrush holder (included).
4. To turn on press the red on/off button. Make sure to turn the compressor off when done.
5. To adjust the pressure use the mode button. There are three power settings indicated by the row of green light. The top green light indicates the highest pressure.
6. When you are done with the compressor for an extended period of time we recommend unplugging the compressor.

Optional Items:

JM#2 Makeup Airbrush



Makeup System Storage Case



WARNING: When a flammable liquid is sprayed, there may be danger of fire or explosion especially in a closed room: keep compressor at least 20 feet away from areas where hazardous concentrations of flammable vapors are likely to occur. Disconnect power before servicing.

ATTENTION: Lorsqu'un liquide inflammable est pulvérisé, il peut y avoir danger d'incendie ou d'explosion, spécialement dans une pièce fermée; garder le compresseur à au moins 20 pieds des endroits où des concentrations dangereuses de vapeurs inflammables sont susceptibles de se produire. Débrancher avant toute maintenance.

Safety Information:

1. Never use in wet location or at high temperatures.
2. Do not spray noxious, flammable or explosive materials.
3. If anything unusual happens disconnect device from power supply immediately.
4. Do not try to repair by yourself.
5. The device is not a toy and should be kept out of the reach of children.
6. Store the compressor in a clean and dry place.
7. Do not run compressor for longer than 20 minutes if the airbrush is not being used.



Paasche Airbrush Company
9511 58th Place, Kenosha, WI 53144
Phone: (800) 621-1907
Website: paascheairbrush.com
E-Mail: info@paascheairbrush.com